

US EPA ARCHIVE DOCUMENT

# Situation Photo Log


Monday, May 28, 2012

Kalamazoo River / Enbridge Spill

**Weather / River Conditions for Monday (5-28-2012)**

Conditions: Sunny

Ambient Air Temperature High: 90° F



Prepared by:  
Timothy Laquerre  
START-USEPA  
Situation Unit Deputy



1. Collection Point at E-4 looking East at the Morrow Lake Delta.



2. Observed sheen at E-3 boat launch.





3. Observed debris and sheen at Ceresco Dam containment.



4. View of Rock Tenn.





5. View looking downstream at Shady Bend Camp Ground.